# Oil Field Environmental Incident Summary

Incident: 20141204111417 Date/Time of Notice: 12/04/2014 11:14
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: FREDERICKS 6-31H

Field Name: HEART BUTTE Well File #: 17634

Date Incident:12/3/2014Time Incident:17:00Facility ID Number:County:DUNNTwp:148Rng:92Sec:6Qtr:

Location Description: Well site, and less than one acre of adjacent property.

Submitted By: Tony Lucero Received By:

Contact Person: Josh Ruffo

US BANK TOWER 950 17TH ST STE 2200 DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:1 MileDistance Nearest Water Well:1 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 30 Barrels 20 Barrels 30 barrels

Brine

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 1/6/2015 Clean Up Concluded: 1/5/2015

Risk Evaluation:

None.

Areal Extent:

Less than one acre.

## Potential Environmental Impacts:

The release affected less than one acre of property adjacent to the well pad.

### Action Taken or Planned:

Clean up has been initiated. Precautions will be taken during future maintenance activities to ensure that the treater is emptied of oil prior to commencing work.

Wastes Disposal Location: Recovered waste material will be sent offsite to an approved disposal

facility.

Agencies Involved: Three Afilliated Tribes (MHA), BIA and BLM

## **Updates**

Date: 12/4/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to a treater leak, sprayed off location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.